


Repair overview of the lower section of the PCV (water stop method by grouting inside vent pipe)



Area subject to repair in the lower section of the PCV

<Overview of repair method>

- (1) Place inflatable bag in the end part of eight vent pipes, and close water path tentatively.
- (2) Stop water flow by gradually grouting upstream of inflatable bag (grout material etc.).
- (3) The S/C will be isolated from the PCV boundary by stopping water flow.